

KST 4UWS			KUT 6			KST 6WS			KUT 10			KUT 16		
6.7 mm (0.26 inch)			8 mm (0.31 Inch)			8 mm (0.31 inch)			10 mm (0.39 inch)			12 mm (0.47 inch)		
46.4 x 42.5 (1.83 x 1.67)			46.4 x 42.5 (1.83 x 1.67)			49.8 x42.5 (1.96 x 1.67)			46.4 x 42.5 (1.83 x 1.67)			51 x 44.5 (2.01 x 1.75)		
4 sq mm			6 sq mm			6 sq mm			10 sq mm			16 sq mm		
0.5 sq mm- 4 sq mm			0.5 sq mm - 6 sq mm			0.5 sq mm - 6 sq mm			1.5 sq mm - 10 sq mm			6 sq mm - 16 sq mm		
0.5 sq mm- 6 sq mm			0.5 sq mm - 10 sq mm			0.5 sq mm - 10 sq mm			1.5 sq mm - 16 sq mm			6 sq mm - 25 sq mm		
12 mm			12 mm			12 mm			12 mm			15 mm		
2 screw clamp & 1 tapped hole for cross connection			2 screw clamp & 1 tapped hole for cross connection			2 screw clamp & 1 tapped hole for cross connection			2 screw clamp and 1 tapped hole for cross connection			2 screw clamp & 1 tapped hole for cross connection		
800 V/32A/4 sq mm/0.5 Nm			800 V/41A/6 sq mm/0.8 Nm			630 V/41A/6 sq mm/0.8 Nm			800 V/57 A/10 sq mm/1.2 Nm			800 V/76 A/16 sq mm/1.2 Nm		
600 V/35 A/10-20 AWG/7 Lbln			600 V/50 A/8-20 AWG/14 Lbln			600 V/40 A/8-20 AWG/12 Lbln			600 V/65 A/6-16 AWG/14 Lbln			600 V/100 A/3-12 AWG/17 Lbln		
M3			M3.5			M3.5			M4			M4		
CAT #	STD. PKG.	WT/STD.PKG-KG	CAT #	STD. PKG.	WT/STD.PKG-KG	CAT #	STD. PKG.	WT/STD.PKG-KG	CAT #	STD. PKG.	WT/STD.PKG-KG	CAT #	STD. PKG.	WT/STD.PKG-KG
KST 4U WS	100	1.28	KUT 6	100	1.51	KST 6 WS	100	1.60	KUT 10	100	2.07	KUT 16	100	2.70
KP X	100	0.31	KPX	100	0.31	KSP 6WS	100	0.52	KPX	100	0.31	KPY	100	0.37
KB X	100	0.46	KBX	100	0.46	KBY	100	0.43	KBX	100	0.46	KB Y	100	0.43
KBXF	100	0.54	KBXF	100	0.54	KBXF	100	0.54	KBXF	100	0.54	KBZF	100	0.75
UHDD	100	0.80	UHDD	100	0.80	UHDD	100	0.80	UHDD	100	0.80	UHDD	100	0.80
PCK	100	7.00	PCK	100	7.00	PCK	100	7.00	PCK	100	7.00	PCK	100	7.00
SCKN	100	0.80	SCKN	100	0.80	SCKN	100	0.80	SCKN	100	0.80	SCKN	100	0.80
SCUN	100	0.94	SCUN	100	0.94	SCUN	100	0.94	SCUN	100	0.94	SCUN	100	0.94
SCUSL	50	0.63	SCUSL	50	0.63	SCUSL	50	0.63	SCUSL	50	0.63	SCUSL	50	0.63
SCUDD	50	0.64	SCUDD	50	0.64	SCUDD	50	0.64	SCUDD	50	0.64	SCUDD	50	0.64
CCLA 2.5 -2W	100	0.56	CCLA 6 -2W	100	0.58	CCLA 6 - 2W	100	0.58	CCLA 10-2W	100	0.76	CCLA 16 - 2W	100	0.83
CCLA 2.5 -3W	100	0.84	CCLA 6 -3W	100	0.86	CCLA 6 - 3W	100	0.86	CCLA 10-3W	100	1.16	CCLA 16 - 3W	100	1.24
CCLA 2.5 -4W	50	0.56	CCLA 6 -4W	50	0.58	CCLA 6 - 4W	50	0.58	CCLA 10-4W	50	0.78	CCLA 16 - 4W	50	0.83
CCLA 2.5 -5W	50	0.69	CCLA 6 -5W	50	0.71	CCLA 6 - 5W	50	0.71	CCLA 10-5W	50	0.98	CCLA 16 - 5W	50	1.04
CCLA 2.5 -10W	25	0.69	CCLA 6 -10W	25	0.72	CCLA 6 - 10W	25	0.72	CCLA 10-10W	25	0.98	--	--	--
PSL 2.5 -2W	100	0.06	PSL 6 - 2W	100	0.08	PSL 6 - 2W	100	0.08	PSL 10-2W	100	0.11	PSL 16 - 2W	100	0.20
PSL 2.5 -3W	100	0.09	PSL 6 - 3W	100	0.12	PSL 6 - 3W	100	0.12	PSL 10-3W	100	0.18	PSL 16 - 3W	100	0.30
PSL 2.5 -4W	100	0.13	PSL 6 - 4W	100	0.16	PSL 6 - 4W	100	0.16	PSL 10-4W	100	0.23	PSL 16 - 4W	100	0.40
PSL 2.5 -5W	100	0.15	PSL 6 - 5W	100	0.20	PSL 6 - 5W	100	0.20	PSL 10-5W	100	0.28	PSL 16 - 5W	100	0.50
PSL 2.5 -10W	100	0.26	PSL 6 - 10W	50	0.20	PSL 6 - 10W	50	0.20	PSL 10-10W	100	0.55	--	--	--
SSP2.5-6	100	0.27	SSP2.5 - 6	100	0.27	SSP2.5-6	100	0.27	SSP10-16	100	0.32	SSP10 -16	100	0.32
SLC 2.5-2W	100	0.23	SLC 6 -2W	100	0.27	SLC 6 -2W	100	0.27	--	--	--	--	--	--
SLC 2.5-3W	100	0.33	SLC 6 -3W	100	0.43	SLC 6 -3W	100	0.43	--	--	--	--	--	--
SLC 2.5-4W	100	0.47	SLC 6 -4W	100	0.59	SLC 6 -4W	100	0.59	--	--	--	--	--	--
SLC 2.5-5W	50	0.29	SLC 6 -5W	50	0.36	SLC 6 -5W	50	0.36	--	--	--	--	--	--
SLC 2.5-10W	50	0.57	SLC 6 -10W	50	0.75	SLC 6 -10W	50	0.75	--	--	--	--	--	--
RSL 2.5	100	0.05	RSL 6	100	0.06	RSL 6	100	0.06	RSL 10	100	0.11	RSL 16	100	0.16
LSR2.5-6	100	0.31	LSR 2.5-6	100	0.31	LSR 2.5-6	100	0.31	LSR 10-16	100	0.49	LSR 10-16	100	0.49
Label KN 6.5	100 Strips	0.10	Label KN 8	100 Strips	0.12	Label KN 8	100 Strips	0.12	Label KN 10	100 Strips	0.15	Label KN 10	100 Strips	0.15
WL 2.5	100	0.31	WL 6	100	0.32	WL 6	100	0.32	WL 10	100	0.42	WL 16	100	0.52
SCKNMLH	50	0.55	SCKNMLH	50	0.55	SCKNMLH	50	0.55	SCKNMLH	50	0.55	SCKNMLH	50	0.55
SCUNMLH	50	0.60	SCUNMLH	50	0.60	SCUNMLH	50	0.60	SCUNMLH	50	0.60	SCUNMLH	50	0.60
KST4UWS(G), KST4UWS(K)			KUT6(G), KUT6(K)			KST6WS(G), KST6WS(K)			KUT10(G), KUT10(K)			KUT16(G), KUT16(K)		
KST4UWS(R), KST4UWS(Y), KST4UWS(B)			KUT6(R), KUT6(Y), KUT6(B)			KST6WS(R), KST6WS(Y), KST6WS(B)			KUT10(R), KUT10(Y), KUT10(B)			KUT16(R), KUT16(Y), KUT16(B)		
KST4UWS(BL), KST4UWS(GR)			KUT6(BL), KUT6(GR)			KST6WS(BL), KST6WS(GR)			KUT10(BL), KUT10(GR)			KUT16(BL), KUT16(GR)		
CHS 3/5/10	100/100/50	22/37/36	CHS 3/5/10	100/100/50	22/37/36	CHS 3/5/10	100/100/50	22/37/36	CHS 3/5/10	100/100/50	22/37/36	CHS 3/5/10	100/100/50	22/37/36
CHK 3/5/10	100/100/100	11/19/36	CHK 3/5/10	100/100/100	11/19/36	CHK 3/5/10	100/100/100	11/19/36	CHK 3/5/10	100/100/100	11/19/36	CHK 3/5/10	100/100/100	11/19/36
CHKS 3/5/10	100/100/100	11/17/34	CHKS 3/5/10	100/100/100	11/17/34	CHKS 3/5/10	100/100/100	11/17/34	CHKS 3/5/10	100/100/100	11/17/34	CHKS 3/5/10	100/100/100	11/17/34
CHKDS 10	50	34.50	CHKDS 10	50	34.50	CHKDS 10	50	34.50	CHKDS 10	50	34.50	CHKDS 10	50	34.50